

1/52




FIG. 1.




FIG. 2.




FIG. 3.




FIG. 4.

2/52




FIG. 5.




FIG. 6.




FIG. 7A.

3/52




FIG. 7B.




FIG. 7H.




FIG. 7C.




FIG. 7D.




FIG. 7E.




FIG. 7F.




FIG. 7G.

6/52

FIG. 8.




FIG. 9.




FIG. 10.





FIG. 11.



7/52




FIG. 12.




FIG. 13.




FIG. 14.




FIG. 15.

FIG. 16.




FIG. 17.





FIG. 18.



9/52




FIG. 19.




FIG. 20.

10/52







FIG. 21.

u/s2 10 Hz
 --- CONTROL — VALVE OPENING — PRESSURE



50 Hz



100 Hz




FIG. 22.

12/52




FIG. 23A.




FIG. 24A.

13/52




FIG. 23B.




FIG. 24B.

14/52




FIG. 25.

15/52




FIG. 26A.




FIG. 26B.




FIG. 27.

17/52




FIG. 28A.




FIG. 28B.

18/52




FIG. 28C.

19/52




FIG. 28D.

20/52




FIG. 29.

21/5.2




FIG. 30.

22/52




FIG. 31A.

23/52




FIG. 31B.

24/52




FIG. 31C.

25/32




FIG. 31D.

26/52




FIG. 32.

27/52




FIG. 33.

28/52









FIG. 34.

2.9/52



[illegible]

31/52




FIG. 38A.




FIG. 39.




FIG. 40.




FIG. 41.




FIG. 42A.




FIG. 42D.




FIG. 42B.




FIG. 42E.




FIG. 42C.




FIG. 42F.




FIG. 42G.




FIG. 42H.




FIG. 42I.




FIG. 42J.

36/52




FIG. 43.




FIG. 44C.




FIG. 44D.




FIG. 44A.




FIG. 44B.

38/52




FIG. 46A.




FIG. 46B.




FIG. 45A.




FIG. 45B.

39/52




FIG. 47.




FIG. 48A.

FIG. 48B.

40/52




FIG. 49.




FIG. 50




FIG. 51




FIG. 52A




FIG. 52B




FIG. 52C




FIG. 52D

FIG. 53




FIG. 54





FIG. 55

FIG. 55B




FIG. 55A




FIG. 55C









FIG. 56

FIG. 58A




FIG. 58B




FIG. 58C





FIG. 58D









FIG. 60

6500

6506













FIG. 60








FIG. 65




FIG. 66





FIG. 68B






FIG. 67

51/52




FIG. 69A




FIG. 69B




FIG. 70